



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

October 4, 2010

Reviewed: 

<b>Mine Name:</b> Jim Gay Mine	<b>Permit Number:</b> M/049/0005
<b>Operator Name:</b> Pabco (Interstate Brick Co.)	<b>Inspection Date:</b> Sept. 20, 2010
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 12:05 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area

#### Inspection Summary:

Permit fees have been remitted for the current year. The reclamation surety is due for escalation – this will be addressed under a separate letter in the near future.

Roger Peck was removing overburden from the southern end of the pit. This material was being hauled to backfill a mined out area. Occasionally the haul truck would traverse an area which would kick up significant dust. Mr. Peck was asked to get a water truck to control dust conditions. The area to the northwest that was reclaimed a couple of years ago was checked. Vegetation is slow to establish on this site. One problem is with the public accessing the site (no fence or gate) to target shoot. There was a significant amount of spent ammo casings on the ground. Associated with this activity was various sorts of debris that was being used for target practice.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

The Division needs to follow up with the surety escalation. Continue to monitor this site when in the area.

#### Inspector's Signature

cc: John Hewett, Interstate Brick Co.

O:\M049-Utah\M0490005-JimGayMine\inspections\insp-09202010.doc